

PINHOLE EXPOSURE CALCULATOR

Instructions

1. Cut around the outer edge of the 3 disks in diagrams 1, 2, and 3. Do not remove the inner white circle in diagrams 1 and 2.
2. Cut out slot in white disk diagram 3 where indicated.
3. Assemble with green Film Speed Disk (diagram 2) in between the other 2 disks.
4. Lighting Conditions

Bright Sunshine	
Partly Cloudy	
Cloudy	
Heavy Cloud	
Indoors Daylight	
Indoor Lighting	

